

# UNITED STATES PATENT AND TRADEMARK OFFICE

UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office Address: COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandria, Virginia 22313-1450 www.uspto.gov

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO	
09/843,781	04/30/2001	Woo Hyuk Choi	041501-5423	1083	
7590 04/20/2004 Morgan, Lewis & Bockins LLP			EXAMINER		
			QI, ZHI QIANG		
1111 PENNSYLVANIA AVENUE, NW Washington, DC 20004			ART UNIT	PAPER NUMBER	
washington, 2	2000.		2871		
			DATE MAILED: 04/20/2004	4	

Please find below and/or attached an Office communication concerning this application or proceeding.

		Application No.	Applicant(s)	119
Office Action Summary		09/843,781	CHOI, WOO HYUK	
		Examiner	Art Unit	
		Mike Qi	2871	
Period fo	The MAILING DATE of this communication ap or Reply	pears on the cover sheet w	ith the correspondence address	
THE - Exte after - If the - If NO - Failu Any	ORTENED STATUTORY PERIOD FOR REPL MAILING DATE OF THIS COMMUNICATION. Insions of time may be available under the provisions of 37 CFR 1. SIX (6) MONTHS from the mailing date of this communication. It is period for reply specified above is less than thirty (30) days, a reply period for reply is specified above, the maximum statutory period are to reply within the set or extended period for reply will, by statutorely received by the Office later than three months after the mailing led patent term adjustment. See 37 CFR 1.704(b).	136(a). In no event, however, may a lily within the statutory minimum of thir will apply and will expire SIX (6) MONe. cause the application to become Af	reply be timely filed  ty (30) days will be considered timely.  ITHS from the mailing date of this communicate  BANDONED (35 U.S.C. § 133).	ion.
Status	•			
1)⊠	Responsive to communication(s) filed on 22 M			
2a) <u></u> ☐	,	s action is non-final.		
3)	Since this application is in condition for allowa			IS
	closed in accordance with the practice under	Ex parte Quayle, 1935 C.L	). 11, 453 O.G. 213.	
Disposit	ion of Claims			
4)[	Claim(s) <u>1,3-9,11-19,21-24,26 and 27</u> is/are p 4a) Of the above claim(s) is/are withdra		•	
5)	Claim(s) is/are allowed.			
	Claim(s) 1,3-9,11-19,21-24,26 and 27 is/are r	ejected.		
	Claim(s) is/are objected to.			
8)	Claim(s) are subject to restriction and/	or election requirement.		
Applicat	tion Papers			
	The specification is objected to by the Examin			
10)	The drawing(s) filed on is/are: a) ac	cepted or b) objected to	by the Examiner.	
	Applicant may not request that any objection to the			1(d)
441	Replacement drawing sheet(s) including the correct The oath or declaration is objected to by the E			
' ' <i>)</i>	The dath of declaration is objected to by the L	Adminor. Note the attache		
-	under 35 U.S.C. § 119			
12)🛛	Acknowledgment is made of a claim for foreig	n priority under 35 U.S.C.	§ 119(a)-(d) or (f).	
a	)⊠ All b) Some * c) None of:			
	1.⊠ Certified copies of the priority documer		Ali-ation No	
	2. Certified copies of the priority documer			
	3. Copies of the certified copies of the pri- application from the International Burea		Treceived in this Mational Olago	
*	See the attached detailed Office action for a lis		t received.	
	Coo and discount dotained Cinico donor. For direct			
Attachme	nt(s)			
1) 🔲 Not	ice of References Cited (PTO-892)		Summary (PTO-413)	
2) Not	ice of Draftsperson's Patent Drawing Review (PTO-948) ormation Disclosure Statement(s) (PTO-1449 or PTO/SB/0	I	(s)/Mail Date Informal Patent Application (PTO-152)	
	ormation Disclosure Statement(s) (PTO-1449 or PTO/SB/06 per No(s)/Mail Date	6)  Other:		

Art Unit: 2871

#### **DETAILED ACTION**

A request for continued examination under 37 CFR 1.114, including the fee set forth in 37 CFR 1.17(e), was filed in this application after final rejection. Since this application is eligible for continued examination under 37 CFR 1.114, and the fee set forth in 37 CFR 1.17(e) has been timely paid, the finality of the previous Office action has been withdrawn pursuant to 37 CFR 1.114. Applicant's submission filed on March 22, 2004 has been entered.

### Response to Amendment

1. The amendment filed on March 22, 2004 is objected to under 35 U.S.C. 132 because it introduces new matter into the disclosure. 35 U.S.C. 132 states that no amendment shall introduce new matter into the disclosure of the invention. The added material which is not supported by the original disclosure is as follows:

Claim 9, recitation ". . . a <u>first one of a data line and a scan line</u> on the substrate; a <u>second one of a data line and a scan line</u> crossing the <u>first one of a data line and a scan line</u> and having first, second and third segments, wherein . . . where the <u>second one of a data line and a scan line</u> and the <u>first one of a data line and scan line</u> overlap; and . . . a repair pattern electrically . . . of <u>the second one of a data line and a scan line</u>, wherein . . . to <u>the second one of a data line and a scan line</u> . . ." in which <u>the first one of a data line and a scan line</u> and the second one of a data line and a scan line do not described in the specification and cannot be found in the figures.

Applicant is required to cancel the new matter in the reply to this Office Action.

Art Unit: 2871

## Claim Rejections - 35 USC § 112

2. The following is a quotation of the first paragraph of 35 U.S.C. 112:

The specification shall contain a written description of the invention, and of the manner and process of making and using it, in such full, clear, concise, and exact terms as to enable any person skilled in the art to which it pertains, or with which it is most nearly connected, to make and use the same and shall set forth the best mode contemplated by the inventor of carrying out his invention.

3. Claims 9-16 and 27 are rejected under 35 U.S.C. 112, first paragraph, as failing to comply with the written description requirement. The claim(s) contains subject matter which was not described in the specification in such a way as to reasonably convey to one skilled in the relevant art that the inventor(s), at the time the application was filed, had possession of the claimed invention.

Claim 9, concerning the "first one of a data line and a scan line" and the "second one of a data line and a scan line" do not described in the specification which is the first one of a data line and a scan line and which is the second one of a data line and a scan line, and where can be found in the figures. The claim 27 indicates the first one of a data line and a scan line is a scan line, and the second one of a data line and a scan line is a data line, in which the first one of a data line and a scan line means the first data line or the first scan line, such that how the first data line or the first scan line is a scan line; and the second one of a data line and a scan line means the second data line or the second data line or the second data line or the second scan line, such that how the second data line or the second scan line is a data line, and it is impossible the second data line crossing the first data line or the second scan line or the second scan line is a data line crossing the first data line or the second scan line is a data line crossing the first data line or the second scan line is a data line crossing the first data line or the second scan line is a data line crossing the first data line or the second scan line is a data line crossing the first scan line.

Art Unit: 2871

The "<u>first one of a data line and a scan line</u>" and the "<u>second one of a data line</u> and a scan line" do not described in the specification, and that a new mater situation is established.

Claims 11-16 and 27 dependent on the claim 9, so that all the dependent claims have the deficiency set forth above.

### Claim Rejections - 35 USC § 103

- 4. The following is a quotation of 35 U.S.C. 103(a) which forms the basis for all obviousness rejections set forth in this Office action:
  - (a) A patent may not be obtained though the invention is not identically disclosed or described as set forth in section 102 of this title, if the differences between the subject matter sought to be patented and the prior art are such that the subject matter as a whole would have been obvious at the time the invention was made to a person having ordinary skill in the art to which said subject matter pertains. Patentability shall not be negatived by the manner in which the invention was made.
- 5. Claims 1, 3-9,11-19, 22-24 and 27 are rejected under 35 U.S.C. 103(a) as being unpatentable over US 5,303,074 (Salisbury) in view of US 5,459,410 (Henley).

Claims 1, 9, 17, 22 and 27, Salisbury discloses (Col.7, line 42 – col.10, line 60; Fig.2B) that a repair structure for a thin film electronic display such as liquid crystal display (LCD) that the scan line or data line is required to isolate a short circuit at the crossover point between the scan line and the gate line, in which the repair structure comprising:

(concerning claims 1, 9, 17, 22 and 27)

- date line (103) and scan line (102) and crossing each other;
- scan line (102) can be shorted to the data line (103) at crossover point (118), and the scan line (102) has been severed at severance points

Art Unit: 2871

(160A, 160B) to electrically isolate the portion of the line with short circuit (150) from remainder of scan line (102) (such that the scan line having first, second and third segments, wherein the second segment "the middle portion" is an electrically isolated from the first and third segments and located at a portion where the scan line and the data line overlap) (see Salisbury in col.8, line 60 – col.9, line 20 and Fig.2B);

- repair lines (122, 123) are electrically insulated from the scan line (102) and data line (103) by a dielectric material such as silicon oxide or silicon nitride (such that the repair pattern electrically isolated from the second segment of the scan line) (see Salisbury in col.7, line 65 col.8, line 3); (concerning claims 17 and 22)
- scan repair line (122) is electrically coupled to its associated scan line (102) at selected location (135) and at the opposite end of scan line (102) (the electrical coupling typically are through contact hole such as the contact (143)), thereby providing a path for electrical signal to be conducted to active components connected to scan line (102) on either side of now isolated segment of the scan line containing shorted area (150) (see Salisbury in col.9, lines 7-20 and Fig.2B);

(concerning claims 1 and 17)

the data line (103) can be bypassed by coupling the data repair line (123) to severing the data line (103) and connecting the selected points (see Salisbury in col.9, lines 21 – 49 and Fig.2B), such that, similarly, the data

Art Unit: 2871

line (103) also can be shorted to the scan line (102) at crossover point (118), and the date line (103) would have been severed at severance points (like the 160A, 160B) to electrically isolate the portion of the line with short circuit (150) from remainder of data line (103) (such that the data line having first, second and third segments, wherein the second segment "the middle portion" is an electrically isolated from the first and third segments and located at a portion where the scan line and the data line overlap).

Salisbury discloses the repair principle and mainly teaches the scan line (102) has been severed at severance points (160A, 160B) to electrically isolate the portion of the line with short circuit (150) from remainder of scan line (102), and that is the same principle as the scan line having first, second and third segments, and the repair pattern electrically isolated from the middle portion (second segment) and electrically connecting the first segment with the third segment of the data line or the scan line. Conventionally, the data lines and scan lines are on a substrate for the liquid crystal display. Even though Salisbury mainly teaches the scan line has been severed, but Salisbury also indicates (col.9, lines 21-31) that likewise, an open circuit on data line (103) can be bypassed by coupling data repair line (123) to it at the selected connection points, so that similarly, the data line (103) also can be shorted to the scan line (102) at crossover point (118), and the date line (103) would have been severed at severance points (like the 160A, 160B) to electrically isolate the portion of the line with short circuit (150) from remainder of data line (103).

Art Unit: 2871

Salisbury does not expressly disclose that the repair pattern bypasses to pixel electrodes adjacent to the data line and has a portion overlapping the pixel electrodes for the claims 1 and 9; and forming an insulating material to fill the portions between the second segment and the first segment of the data lines (or the scan lines) and between the second segment and the third segment of the data lines (or the scan lines) for the claims 17 and 22.

However, Henley discloses (col.11, line 65 – col.12, line 6; Fig.12c) that a cross-short repair structure that the scan line (15) is cut at locations (80,82) to sever the short circuit, and using laser removes passivation from the scan line in areas (84,86) to form a conductive bridge (88) which contacts each area (84,86) without shorting data line (13). Because the gate line (scan line) and the data line form the pixel region, as shown in Figs.6 and 14, and the repair pattern is a conductive bridge across the pixel region as shown in Fig.12c. The figures 6 and 14 show an electrical diagram that does not show the precise distance, and the figures show that the principle of the pixel region are defined by the data line and the gate line, and normally, the desirable pixel region is as larger as possible in order to enlarge the display area. Therefore, when forming the conductive bridge, the repair pattern must have a portion of the conductive bridge must have a portion overlapping the pixel electrodes.

Henley indicates (col.2, lines 15-18) such repair structure improving the production yields, especially, for assembling high density active matrix LCD panels.

Art Unit: 2871

Therefore, it would have been obvious to those skilled in the art at the time the invention was made to arrange a repair pattern as claimed in claims 1, 9 and 27 for improving the production yields of the high density active matrix LCD display.

Salisbury disclosed (col.7, line 65 – col.8, line 3) that electrically insulating the conductive lines (such as the repair lines and the transmission lines, all of them are conductive lines) are typically by forming an intermediate layer of dielectric material such as silicon oxide or silicon nitride between the conductive lines.

Although Salisbury does not expressly discloses forming an insulating material to fill the portions between the second segment and the first segments of the data lines (or the scan lines) and between the second segment and the third segments of the data lines (or the scan lines), but to insulate the two conductive segments using insulating material that is the same principle as to insulate the repair lines and the transmission lines as Salisbury disclosed (col.7, line 65 – col.8, line 3) that using silicon oxide or silicon nitride, i.e., insulating material, to insulate the two conductive lines, and that is a conventional technique filling an insulating material between the two conductive segments in order to insulate the two conductive segments, because the insulating material has a reliable insulating property.

Therefore, it would have been obvious to those skilled in the art at the time the invention was made to fill an insulating material into the portions between the segments of the data lines or scan lines as claimed in claims 17 and 20 in order to obtain a reliable insulation between the conductive segments.

Art Unit: 2871

<u>Claims 3, 6, 11 and 14</u>, the lacking limitation is such that the repair pattern overlapping the pixel electrodes and having a "[" shape.

However, Henley discloses (col.11, line 65 – col.12, line 6; Fig.12c) that a crossshort repair structure that the scan line (15) is cut at locations (80,82) to sever the short circuit, and using laser removes passivation from the scan line in areas (84,86) to form a conductive bridge (88) which contacts each area (84,86) without shorting data line (13). Because the gate line (scan line) and the data line form the pixel, as shown in Figs.6 and 14, and the repair pattern is a conductive bridge across the pixel region as shown in Fig.12c. The figures 6 and 14 show an electrical diagram that does not show the precise distance, and the figures show that the principle of the pixel region are defined by the data line and the gate line, and normally, the desirable pixel region is as larger as possible in order to enlarge the display area. Therefore, when forming the conductive bridge, the repair pattern must have a portion of the conductive bridge bypassing to pixel electrodes adjacent to the data line and the conductive bridge must have a portion overlapping the pixel electrodes. In order to avoid short-circuit the bridge (88) to the pixel electrodes, the overlapping portion of the pixel electrodes with the bridge (88) must be isolated from other portion of the pixel electrodes, and the repair bridge (88) has a "[" shape.

Henley indicates (col.2, lines 15-18) such repair structure improving the production yields, especially, for assembling high density active matrix LCD panels.

Art Unit: 2871

Therefore, it would have been obvious to those skilled in the art at the time the invention was made to arrange a repair pattern as claimed in claims 3, 6, 11 and 14 for improving the production yields of the high density active matrix LCD display.

<u>Claims 4, 7, 12 and 15</u>, the lacking limitation is such that the repair pattern is a "I" shape.

However, the "I" shape repair pattern that is using the same principle to cut the scan line or the data line along the upper portion of the scan line or the data line, and severing into segments to repair the cross-short circuit line between the scan line and the data line, and the repair pattern must be "I" shape, and that would have been an obvious variation.

<u>Claims 5 and 13</u>, Salisbury disclosed (col.7, line 65 – col.8, line 3) that electrically insulating the conductive lines (such as the repair lines and the transmission lines, all of them are conductive lines) are <u>typically by forming an intermediate layer</u> of dielectric material such as silicon oxide or silicon nitride between the conductive lines.

Although Salisbury does not expressly discloses forming an insulating material to fill the portions between the second segment and the first segments of the data lines (or the scan lines) and between the second segment and the third segments of the data lines (or the scan lines), but to insulate the two conductive segments using insulating material that is the same principle as to insulate the repair lines and the transmission lines as Salisbury disclosed (col.7, line 65 – col.8, line 3) that using silicon oxide or silicon nitride, i.e., insulating material, to insulate the two conductive lines, and that is a conventional technique filling an insulating material between the two conductive

Art Unit: 2871

segments in order to insulate the two conductive segments, because the insulating material such as silicon oxide or silicon nitride has the insulating property.

Therefore, it would have been obvious to those skilled in the art at the time the invention was made to fill an insulating material into the portions between the segments of the data lines or scan lines as claimed in claims 5 and 13 in order to obtain the insulation between the conductive segments

Claims 8 and 16, Salisbury discloses (col.7, lines 65-67) that the repair lines (122, 123) are electrically conductive, and using the conductive material such as metal as the repair pattern that would have been at least obvious.

Claim 18-19 and 23-24, Salisbury discloses (col.7, lines 48 – 51) that severing or cutting (electrically isolating) of a transmission line (such as the scan line or the data line or forming a contact hole) is normally accomplished with a laser cutting, and that would have been at least obvious.

6. Claims 21 and 26 are rejected under 35 U.S.C. 103(a) as being unpatentable over Salisbury and Henley as applied to claims 1, 3-9,11-19, 22-24 and 27 above, and further in view of US 5,407,701 (Baum et al).

Claims 21 and 26, the lacking limitation is such that using laser to form the repair pattern.

However, Baum discloses (col.1 line 30 – col.2, line 42) that using laser-induced chemical vapor deposition (LCVD), and a focused laser is utilized to heat the surface of a substrate at an open region between two separated circuit lines in the presence of a gaseous reactive compound, so that the formation of an interconnecting circuit line has

Art Unit: 2871

high electrical conductivity and high metallic purity without any carbon/oxygen incorporation.

Therefore, it would have been obvious to those skilled in the art at the time the invention was made to use laser-induced chemical vapor deposition for the repair pattern as claimed in claims 21 and 26 for achieving high electrical conductivity in the formation of the interconnecting circuit lines such as the data line or the scan line.

### Response to Arguments

7. Applicant's arguments filed on Jul.10, 2003 have been fully considered but they are not persuasive.

# Applicant's only arguments are as follows:

- 1) The references do not teach or suggest that the repair pattern bypasses to pixel electrodes adjacent to the data line (or scan line) and has a portion overlapping the pixel electrodes as claimed in claims 1 and 9.
- 2) The references do not teach or suggest that forming an insulating material to fill portions between the first and second segments of the data lines (or the scan lines) and between the second and third segments of the data lines (or the scan lines) as claimed in claims 17 and 22.
  - 3) The office action does not show any motivation to combine the reference. Examiner's responses to Applicant's **only** arguments are as follows:
  - 1) The reference Henley discloses (col.11, line 65 col.12, line 6; Fig.12c) a

Art Unit: 2871

cross-short repair structure that the scan line (15) is cut at locations (80,82) to sever the short circuit, and using laser removes passivation from the scan line in areas (84,86) to form a conductive bridge (88) which contacts each area (84,86) without shorting data line (13). Because the gate line (scan line) and the data line form the pixel region, as shown in Figs.6 and 14, and the repair pattern is a conductive bridge across the pixel region as shown in Fig.12c. The figures 6 and 14 show an electrical diagram that does not show the precise distance, and the figures show that the principle of the pixel region are defined by the data line and the gate line, and normally, the desirable pixel region is as larger as possible in order to enlarge the display area. Therefore, when forming the conductive bridge, the repair pattern must have a portion of the conductive bridge bypassing to pixel electrodes adjacent to the data line and the conductive bridge must have a portion overlapping the pixel electrodes. Henley indicates (col.2, lines 15-18) such repair structure improving the production yields, especially, for assembling high density active matrix LCD panels.

2) Salisbury disclosed (col.7, line 65 – col.8, line 3) that electrically insulating the conductive lines (such as the repair lines and the transmission lines, all of them are conductive lines) are typically by forming an intermediate layer of dielectric material such as silicon oxide or silicon nitride between the conductive lines. Although Salisbury does not expressly discloses forming an insulating material to fill the portions between the second segment and the first segments of the data lines (or the scan lines) and between the second segment and the third segments of the data lines (or the scan lines), but to insulate the two conductive segments using insulating material that is the

Art Unit: 2871

same principle as to insulate the repair lines and the transmission lines as Salisbury disclosed using silicon oxide or silicon nitride, i.e., insulating material, to insulate the two conductive lines, and that is a conventional technique filling an insulating material between the two conductive segments in order to insulate the two conductive segments, because the insulating material such as silicon oxide or silicon nitride has a reliable insulating property.

3) In response to applicant's argument that there is no suggestion to combine the references, the examiner recognizes that obviousness can only be established by combining or modifying the teachings of the prior art to produce the claimed invention where there is some teaching, suggestion, or motivation to do so found either in the references themselves or in the knowledge generally available to one of ordinary skill in the art. See In re Fine, 837 F.2d 1071, 5 USPQ2d 1596 (Fed. Cir. 1988) and In re Jones, 958 F.2d 347, 21 USPQ2d 1941 (Fed. Cir. 1992). In this case, the reference Salisbury discloses (col.1, line 48 – col.5, line 57) that a short circuit between a data line and a scan line leads to inaccurate signals being applied to all switching transistors connected to either of the shorted data line or scan line. Salisbury disclosed a same principle to form the repair pattern as this application. The reference Henley discloses (col.1, line 24 - col.4, line 3) that conventional display panel manufacturing yields have been unsatisfactory, causing display panel cost to be a large portion of the final cost. The reference Henley discloses a method for testing and repairing an active matrix LCD panel using conductive bridge by laser to isolate the short circuit, and such that improves the production yields, especially for assembling high density active matrix

Art Unit: 2871

LCD panel, and that would be the benefit for producing this invention, and the motivation exists.

#### Conclusion

- 8. The prior art made of record and not relied upon is considered pertinent to applicant's disclosure.
- 9. Any inquiry concerning this communication or earlier communications from the examiner should be directed to Mike Qi whose telephone number is (571) 272-2299. The examiner can normally be reached on M-T 8:00 am-5:00 pm.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Robert Kim can be reached on (571) 272-2293. The fax phone number for the organization where this application or proceeding is assigned is 703-872-9306.

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free).

Mike Qi April 7, 2004 DUNGT. NGUYEN PRIMARY EXAMINER